

Directions for Application of CE 1000

Where to Use:

- 1. This product is specifically designed to be used as a color enhancer for different hard surfaces.
- 2. It is also used for polishing purposes.
- 3. Made of plant extracts and is non-toxic.

Supplies Needed:

- 1. CE-1000

CE-1000 - 36/8oz Bottles with Sprayer	JCCEM368OB
CE-1000 – 2/1 Gallon Bottles	JCCEM2Z1GB

- 2. Non-Shedding cleaning cloth

Preparing the surface:

- 1. Ensure that the surface is clean and free from debris, oils, grease and organic material.
- 2. The surface must be dry before applying CE-1000 when using any cleaner.

Application of CE-1000

- 1. With the tip of the spray applicator 4 to 6 inches above the surface, apply a small amount (2” dia) of the CE-1000 to the middle of a 3’ X 3’ area.
- 2. Using the cloth, spread all over the surface in a circular polishing motion to ensure complete coverage.
- 3. Allow to dry. Product lasts 2-4 week depending on use of the surface.

A New Era of Scientific Solutions for Your Peace of Mind